

Home
Products
Electro Field Meter
Charge Plate Monitors
TERA Ohmmeter
WS- and Shoe Testers
PGT 50
PMS 300
SST 200
SST 210
WST 50
WST 100
Prices
Support
Suche
<input type="text"/> <input type="button" value="Go"/>

[Products](#) > [WS- and Shoe Testers](#) > [PMS 300](#)

PMS 300

The PMS 300 work station monitor is suited for the permanent supervision of a ESD protected working space. It has the following properties:



Wrist strap

The correct wearing and the function of up to two divided wrist straps can be checked.

Desk pads

The conductivity of the desk pad can be tested.

Audio warning

Audio warning over the disengageable buzzer.



Status display

The operating status of the device and the test results are displayed with LEDs in different colors.

Several operation modes

The device can be driven in different operation modes. E.g. the desk pad check can be disengaged.

Compatibility

Thanks to different adapters the PMS 300 is compatible to all established types of wrist straps.

Specifications:

Dimensions:	Aluminium housing 113mm x 30mm x 105mm (W x L x D)
Weight:	approx. 100g
Power supply:	Mains adapter PW-75-150 7,5V 150mA
Display	6 LEDs, buzzer
Measuring principle:	Resistance measurement
Connectors:	on the backside over several plugs
Tresholds:	adjustable over reference resistors

Scope of delivery

- PMS 300
- Mains adapter PW75-150
- Connection box C2

